




BLASTING TIPS



GAP METHOD - BLAST PATTERN EFFICIENCY


The pattern you blast with can have a large effect on the amount of surface area you can blast in a specific time. The typical way most people blast creates an unnecessarily large area of overlap. By blasting and leaving a gap between passes equal to 1/2 the width of the blast pattern and blasting the gap the second time around, you force yourself to overlap the proper amount.

MORE COVERAGE
SAME TIME
SAME WEAR & TEAR
SAME MEDIA USAGE



Your Pirate Brand Distributor:

Typical Overlap Method (Mostly Overlap - Less Coverage)



50% Gap Method (Less Overlap - More Coverage)

